Approved For Release 2008/02/06 : CIA-RDP78B04558A000900010089-5

OUT 4793

6 JAN 1965

1965 JAN 5 21

P 052057Z
FM NPIC WASHDC
TO RUCSC/SAC OFFUTT AFB OMAHA NEB
RUCVAA/4080 STRAT WG OL 19 BARKSDALE AFB LA
RUCVAA/2D RTS BARKSDALE AFB LA
RUEAHQ/DIA WASHDC
RUECYH/NAVRECONTECHSUPPCEN SUITLAND MD
RUEPIA/CIA WASHDC
RUWBKN/15TH AF MARCH AFB RIVERSIDE CALIF
RUWGAA/2AF BARKSDALE AFB LA
BT
S E C R E T CITE NPIC 3609.

COPIES RECEIVED 7			
CyNo.	Office	Act.	Rec'd
1	Master File		
	OS		
	ADMIN		
	SEC BR		
	P&DS		
	CSD		
	IPD		
	PD		
	PSD		
3	TID	✓	
	PAG		
	DIAPIC		
	DIAXX-4		
	NSA LO		
	DIAAP		
	Destroyed		

15TH AF (FOR DI), SAC (FOR DIM/GOLDEN TREE/DOCR, DM 4) 2D AF (FOR DI)

1. CAMERA B-101 WAS USED IN MISSION 3981 FLOWN ON 3 JANUARY 1965. PROCESSING WAS ACCOMPLISHED BY BARKSDALE AFB.

2. ORIGINAL NEGATIVE:

A. THE EXPOSURE WAS ADEQUATE AND THE RESOLUTION IS GOOD.

B. 9R SIDE: A THREAD-LIKE OBSTRUCTION, APPROXIMATELY 0.4" LONG, ADHERING TO THE EDGE OF THE DATA CHAMBER IS PRESENT ON ALL FRAMES. A CLUSTER OF MINUS DESNTITY DOTS, UP TO 30 IN NUMBER, IS PRESENT IN THE OUTBOARD CORNERS OF EACH FORMAT THROUGHOUT THE MISSION. ANOTHER CLUSTER OF FOUR MINUS DENSITY DOTS OCCURS NEAR EACH FORMAT CENTER ON THE FIRST 1321 FRAMES. SPOT STATIC DISCHARGES OCCUR INTERMITTENTLY ALONG THE INBOARD EDGE OF THE FILM THROUGHOUT THE MISSION. NUMEROUS SHORT ABRASIONS, ACROSS THE ENTIRE FORMAT AND ROUGHLY PARALLEL TO THE FILM EDGES, ARE PRESENT ON FRAMES 900 THROUGH 1450. MARKING PEN INK IS TRANSFERRED FROM THE HEAD LEADER TO THE FIRST FRAME (1200) PART 5. IRREGULAR PLUS DENSITY STREAKS OCCUR INTERMITTENTLY ON FRAMES 2125 THROUGH 2147 (END). A MANUFACTURER'S SPLICE IS MADE IN FRAME 343.

C. 9L SIDE: MINUS DENSITY DOTS, SPACED 1.55" APART, ARE LOCATED

GROUP 1
Excluded from automatic downgrading and declassification

SECRET

Approved For Release 2008/02/06 : CIA-RDP78B04558A000900010089-5

Approved For Release 2008/02/06 : CIA-RDP78B04558A000900010089-5

AT THE FOLLOWING DISTANCES FROM THE OUTBOARD EDGE OF THE FILM: 1.9" IN FRAMES 000 TO 005, 2.4" IN FRAME 754, 1.1" IN FRAMES 1426 TO 1429, AND 1.5" IN FRAME 1841. THERE ARE ALSO MANY SCATTERED MINUS DENSITY DOTS CONTAINED IN FRAME 002. TWO MINUS DENSITY DOTS LOCATED 1.5" AND 1.8" FROM THE OUTBOARD EDGE AND 0.7" FROM THE SUPPLY SIDE OF THE FORMAT ARE PRESENT IN EACH FRAME FROM 950 TO THE END OF THE MISSION. SEVERAL CHEMICAL SPOTS WERE NOTED ON THE EMULSION FROM FRAME 757 TO THE END OF THE MISSION. A CRESCENT SHAPED FOG PATCH 1.5" TO 2.5" LONG IS LOCATED ABOUT 6.5" FROM THE TAKE-UP SIDE OF THE FORMAT AND 2.5" FROM THE OUTBOARD EDGE OF THE FILM. THIS PATCH OF FOG IS PRESENT THROUGHOUT THIS MISSION AND IT HAS BEEN REPORTED ON PREVIOUS MISSIONS.

D. BOTH SIDES: OUTBOARD EDGE FOG IS PRESENT THROUGHOUT THE MISSION. THE TITLED FRAMES ON EACH SIDE ARE NUMBERED FROM 0000 TO 2147.

E. THERE WERE NO MAJOR CAMERA OR PROCESSING MALFUNCTIONS DURING THE MISSION.

3. POSITIVE:

A. THE PI SUITABILITY IS GOOD.

B. THE PRINTING AND PROCESSING WAS GOOD.

C. CLOUDS DEGRADED APPROXIMATELY 25 PERCENT OF THE MISSION.

S E C R E T

-END OF MESSAGE-

Approved For Release 2008/02/06 : CIA-RDP78B04558A000900010089-5